






VACCUM FORM windscreen



SPARK PLUG CABLE 350mm



WIRE brass

Resin parts x 3

TYRE rubber x 4


SPRINGS steel x 4



TRUMPETS aluminium x 8




AIR FUNNEL steel x 2







• Tube Exhaust steel x 2



Turned piece aluminum x 1

Metal Parts 1978 Austria GP- GP20085







Bend equal the drawing



Bend equal the drawing



- | | | | |
|-----|------|-----|------|
| M21 | M25A | M28 | M66 |
| M30 | M56 | M29 | M67 |
| M35 | | M33 | M69 |
| M36 | | M38 | M70 |
| M42 | | M39 | M71 |
| M47 | | M48 | M72 |
| M48 | | M49 | M27A |
| M51 | | M53 | M27B |
| M55 | | | |
| M38 | | | |



Use a drill in the measure 0.7mm to hole all holes used by these screws.

